

Rainbow District School Board

Event Listing By Ascending Event Year

Major Facility Needs - Details - Supplement to Section 2.2 of the School Information Profile

Webbwood PS, Campus ID 6870

| Element | Event | Year | Cost |
|---|---|------|---------------------|
| B2020 Exterior Windows - Entire Building | Replacement [B2020 Exterior Windows - Entire Building] | 2014 | \$ 178,464 |
| B3010 Roof Coverings - Main Bldg, - All | Replacement [B3010 Roof Coverings - Main Bldg, - All] | 2014 | \$ 363,395 |
| C1030 Fittings - Millworks - Entire Building | Replacement [C1030 Fittings - Millworks - Entire Building] | 2014 | \$ 113,561 |
| D2010 Plumbing Fixtures - All | Replacement [D2010 Plumbing Fixtures - Original Building, 1959 & 1972 Additions] | 2014 | \$ 66,781 |
| D2020 Domestic Water Distribution - Piping Systems - Study & Replace | .Study [D2020 Domestic Water Distribution - Piping Systems] | 2014 | \$ 131,731 |
| G204001 Fencing & Gates | Replacement [G204001 Fencing & Gates] | 2014 | \$ 40,882 |
| D302002 Hot Water Boilers | Replacement [D302002 Hot Water Boilers] | 2014 | \$ 125,171 |
| D3010 Energy Supply - Heating Oil Tank | Replacement [D3010 Energy Supply - Heating Oil Tank] | 2014 | \$ 63,648 |
| D3050 Terminal & Package Units - All | Replacement [D3050 Terminal & Package Units - All] | 2014 | \$ 90,849 |
| C1030 Fittings - Washroom Partitions - Entire Building | Replacement [C1030 Fittings - Washroom Partitions - Entire Building] | 2014 | \$ 34,532 |
| D304003 Heating/Chilling water distribution systems - Study & Replace - All | Replacement [D304003 Heating/Chilling water distribution systems - All] | 2014 | \$ 215,766 |
| D304007 Exhaust Systems - All | Replacement [D304007 Exhaust Systems - All] | 2014 | \$ 31,797 |
| D2020 Domestic Water Distribution - Sanitary Lines | Replacement [D2020 Domestic Water Distribution - Sanitary Lines] | 2014 | \$ 130,122 |
| D501003 Main Switchboards - Main Disconnect & Distribution Panels | Replacement [D501003 Main Switchboards] | 2014 | \$ 124,800 |
| G204007 Playing Fields - Asphalt Paved | Replacement [G204007 Playing Fields - Asphalt Paved] | 2014 | \$ 74,950 |
| G204007 Playing Fields - Unpaved | Major Repair [G204007 Playing Fields - Unpaved] | 2014 | \$ 68,137 |
| D302005 Auxiliary Equipment - Boiler Expansion Tank | Replacement [D302005 Auxiliary Equipment - Boiler Expansion Tank] | 2014 | \$ 6,814 |
| D302005 Auxiliary Equipment - Stack & Breaches | Replacement [D302005 Auxiliary Equipment - Stacks & Breaches] | 2014 | \$ 28,390 |
| A1010 Standard Foundations- Parging - Entire Building | Replacement [A1010 Standard Foundations- Parging - Entire Building] | 2014 | \$ 30,661 |
| B2030 Exterior Doors - Entire Building | Replacement [B2030 Exterior Doors - Entire Building] | 2014 | \$ 36,000 |
| B2010 Exterior Walls - Entire Building | Replacement [B2010 Exterior Walls - Entire Building] | 2014 | \$ 278,225 |
| G301001 Well Systems | Study [G301001 Well Systems] | 2014 | \$ 4,633 |
| G301001 Well Systems | Replacement [G301001 Well Systems] | 2014 | \$ 46,326 |
| G302005 Septic Tanks | Replacement [G302005 Septic Tanks] | 2014 | \$ 21,715 |
| G2020 Parking Lots - Gravel Paved | Replacement [G2020 Parking Lots - Gravel Paved] | 2015 | \$ 45,424 |
| C3020 Floor Finishes - Vinyl Floor Tile - Entire Building | Replacement [C3020 Floor Finishes - Vinyl Floor Tile - Entire Building] | 2015 | \$ 68,137 |
| | Backlog | | \$ 2,420,911 |
| C1020 Interior Doors | Replacement [C1020 Interior Doors] | 2016 | \$ 55,424 |
| D502002 Lighting Equipment - Interior - All | Replacement [D502002 Lighting Equipment - Addn1] | 2016 | \$ 79,493 |
| D2020 Domestic Water Distribution - DHW | Replacement [D2020 Domestic Water Distribution] | 2016 | \$ 6,814 |
| D2020 Domestic Water Distribution - Plumbing Pumps | Replacement [D2020 Domestic Water Distribution] | 2016 | \$ 4,542 |
| D302099 Other Heat Generating Systems - Heat&Cool | Major Repair [D302099 Other Heat Generating Systems - Heat&Cool] | 2016 | \$ 90,849 |
| D502002 Lighting Equipment - Emergency Lighting - All | Replacement [D502002 Lighting Equipment - All] | 2016 | \$ 7,949 |
| D502002 Lighting Equipment - Exterior - All | Replacement [D502002 Lighting Equipment - Exterior - All] | 2016 | \$ 3,407 |
| D302005 Auxiliary Equipment | Replacement [D302005 Auxiliary Equipment] | 2016 | \$ 11,356 |
| C3030 Ceiling Finishes - Suspended Acoustic Panel Ceiling - Entire Building | Replacement [C3030 Ceiling Finishes - Suspended Acoustic Panel Ceiling - Entire Building] | 2016 | \$ 49,032 |
| C1030 Fittings - Window Coverings | Replacement [C1030 Fittings - Window Coverings] | 2020 | \$ 9,085 |
| C3010 Wall Finishes - All | Replacement [C3010 Wall Finishes - All] | 2020 | \$ 54,509 |
| G30 Site Civil/Mechanical Utilities | Replacement [G30 Site Civil/Mechanical Utilities] | 2020 | \$ 415,420 |
| G40 Site Electrical Utilities | Replacement [G40 Site Electrical Utilities] | 2020 | \$ 28,788 |
| G204007 Playing Fields | Replacement [G204007 Playing Fields] | 2020 | \$ 82,900 |
| G2020 Parking Lots | Replacement [G2020 Parking Lots] | 2020 | \$ 27,225 |
| G2050 Landscaping | Replacement [G2050 Landscaping] | 2020 | \$ 65,865 |
| G2010 Roadways | Replacement [G2010 Roadways] | 2020 | \$ 22,712 |
| D503001 Fire Alarm Systems - All | Replacement [D503001 Fire Alarm Systems] | 2020 | \$ 12,492 |
| C3020 Floor Finishes - Carpeting | Replacement [C3020 Floor Finishes - Addn2] | 2020 | \$ 14,309 |
| C1030 Fittings - Lockers | Replacement [C1030 Fittings - Lockers] | 2020 | \$ 40,882 |
| C3020 Floor Finishes - Addn1 | Replacement | 2020 | \$ 13,627 |
| | Backlog + 5 Years | | \$ 3,517,591 |
| Date Report Generated | 1/19/2016 | | |

| Door & Windows | Infrastructure | Interior Finishes | Mechanical | Electrical | Site Work |
|-------------------|-------------------|-------------------|---------------------|-------------------|-------------------|
| \$ 178,464 | | | | | |
| | \$ 363,395 | | | | |
| | | \$ 113,561 | | | |
| | | \$ 66,781 | | | |
| | | | \$131,731 | | |
| | | | | | \$ 40,882 |
| | | | \$125,171 | | |
| | | | \$63,648 | | |
| | | | \$90,849 | | |
| | | \$ 34,532 | | | |
| | | | \$215,766 | | |
| | | | \$31,797 | | |
| | | | \$130,122 | | |
| | | | | \$ 124,800 | |
| | | | | | \$ 74,950 |
| | | | | | \$ 68,137 |
| | | | \$6,814 | | |
| | | | \$28,390 | | |
| | \$ 30,661 | | | | |
| \$ 36,000 | | | | | |
| | \$ 278,225 | | | | |
| | | | \$4,633 | | |
| | | | \$46,326 | | |
| | | | \$21,715 | | |
| | | | | | \$ 45,424 |
| | | \$ 68,137 | | | |
| | | | | | |
| \$ 55,424 | | | | \$ 79,493 | |
| | | | \$6,814 | | |
| | | | \$4,542 | | |
| | | | \$90,849 | | |
| | | | | \$ 7,949 | |
| | | | | \$ 3,407 | |
| | | | \$11,356 | | |
| | | \$ 49,032 | | | |
| | | \$ 9,085 | | | |
| | | \$ 54,509 | | | |
| | | | | | \$ 415,420 |
| | | | | | \$ 28,788 |
| | | | | | \$ 82,900 |
| | | | | | \$ 27,225 |
| | | | | | \$ 65,865 |
| | | | | | \$ 22,712 |
| | | | | \$ 12,492 | |
| | | \$ 14,309 | | | |
| | | \$ 40,882 | | | |
| | | \$ 13,627 | | | |
| \$ 269,888 | \$ 672,281 | \$ 464,455 | \$ 1,010,523 | \$ 228,141 | \$ 872,303 |

Note: This report was generated directly from the Ministry of Education Total Capital Planning Solutions (TCPS) database. It provides more information about the Major Facility Needs - 5 Year Projection to supplement Section 2.2 of the School Information Profile.