Rainbow District School Board

Event Listing By Ascending Event Year

Major Facility Needs - Details - Supplement to Section 2.2 of the School Information Profile

| Element | Event | Year | Year Cost | |
|---|--|--------------|-----------------------|--|
| C1020 Interior Doors | Replacement [C1020 Interior Doors] | 2014 | \$85,170 | |
| C3010 Wall Finishes - Paint Wallcovering | Replacement [C3010 Wall Finishes - Paint Wallcovering] | 2014 | \$65,70 | |
| 32020 Exterior Windows | Replacement [B2020 Exterior Windows] | 2014 | \$91,26 | |
| B3010 Roof Coverings | Replacement [B3010 Roof Coverings] | 2014 | \$395,460 | |
| D503004 Public Address Systems | Replacement [D503004 Public Address Systems] | 2014 | \$54,75 | |
| C1030 Fittings - Washroom Partitions | Replacement [C1030 Fittings - Washroom Partitions] | 2014 | \$17,96 | |
| D2010 Plumbing Fixtures | Replacement [D2010 Plumbing Fixtures] | 2014 | \$49,21 | |
| G2030 Pedestrian Paving | Replacement [G2030 Pedestrian Paving] | 2014 | \$67,73 | |
| D304003 Heating/Chilling Water piping Systems - Study & Replace | Replacement [D304003 Heating/Chilling water distribution systems] | 2014 | \$155,664 | |
| D3050 Terminal & Package Units - Hydronic Heating | Replacement [D3050 Terminal & Package Units] | 2014 | \$60,84 | |
| C3020 Floor Finishes - Sheet Vinyl | Replacement [C3020 Floor Finishes - Sheet Vinyl] | 2014 | \$79,693 | |
| D3010 Energy Supply - Natural Gas Piping | Replacement [D3010 Energy Supply - Natural Gas Piping] | 2014 | \$15,939 | |
| D502002 Lighting Equipment - Exterior Lighting | Replacement [D502002 Lighting Equipment] | 2014 | \$3,985 | |
| D502002 Lighting Equipment - Emergency Lighting | Replacement [D502002 Lighting Equipment - Emergency Lighting] | 2014 | \$12,168 | |
| D2020 Domestic Water Distribution - Domestic Water Piping - Study & Replace | Replacement [D2020 Domestic Water Distribution - Domestic Water Piping] | 2014 | \$133,754 | |
| C3020 Floor Finishes - Carpeting | Replacement [C3020 Floor Finishes - Carpeting] | 2014 | \$14,942 | |
| D501003 Main Switchboards | Replacement [D501003 Main Switchboards] | 2014 | \$54,756 | |
| D302005 Auxiliary Equipment - Stacks and Breaching | Replacement [D302005 Auxiliary Equipment - Stacks and Breaching] | 2014 | \$22,912 | |
| D304001 Air Distribution, Heating & Cooling - Ductwork - Study & Replace | Replacement [D304001 Air Distribution, Heating & Cooling - Ductwork] | 2014 | \$139,578 | |
| D502001 Branch Wiring - Electrical Distribution - Study & Replace | Replacement [D502001 Branch Wiring - Electrical Distribution] | 2014 | \$3,98 | |
| D502001 Branch Wiring - Electrical Distribution - Study & Replace | .Study [D502001 Branch Wiring - Electrical Distribution] | 2014 | \$109,57 | |
| D302001 Branch Wining - Electrical Distribution - Study & Replace | Replacement [D302002 Hot Water Boilers - RTU] | 2014 | \$84,689 | |
| A1010 Standard Foundations - Parging | | 2014 | \$29,88 | |
| | Replacement [A1010 Standard Foundations - Parging] | | | |
| B2010 Exterior Walls - Wood Siding B2010 Exterior Walls | Replacement [B2010 Exterior Walls - Wood Siding] Repairs [B2010 Exterior Walls] | 2014 2014 | \$83,678 \$139,463 | |
| | | | | |
| B2030 Exterior Doors - Wood Framed Glass Double | Replacement [B2030 Exterior Doors - Wood Framed Glass Double] | 2014 | \$58,406 | |
| D302005 Auxiliary Equipment - HVAC Pumps | Replacement [D302005 Auxiliary Equipment] | 2014 | \$19,962 | |
| C1010 Partitions | Replacement [C1010 Partitions] - Carpentry | 2014 | \$179,30 | |
| D304007 Exhaust Systems - Rooftop Mounted Exhaust Fans | Replacement [D304007 Exhaust Systems - Rooftop Mounted Exhaust Fans] | 2015 | \$181,712 | |
| B2030 Exterior Doors - Hollow Metal | Replacement [B2030 Exterior Doors - Hollow Metal] | 2015 | \$21,902 | |
| G204001 Fencing & Gates | Replacement [G204001 Fencing & Gates] | 2015 | \$43,83 | |
| C3020 Floor Finishes - Vinyl Floor Tiles | Replacement [C3020 Floor Finishes - Vinyl Floor Tiles] | 2015 | \$79,693 | |
| C3030 Ceiling Finishes - Suspended Acoustic Panel Ceiling | Replacement [C3030 Ceiling Finishes - Suspended Acoustic Panel Ceiling] | 2015 | \$59,770 | |
| | Backlog | | \$2,617,372 | |
| D3060 Controls & Instrumentation - Building | Replacement [D3060 Controls & Instrumentation] | | \$47,816 | |
| D303099 Other Cooling Generating Systems | Replacement [D303099 Other Cooling Generating Systems] | | \$25,900 | |
| G204005 Signage - New Logo | Replacement [G204005 Signage - New Logo] | 2016 | \$29,88 | |
| G30 Site Civil/Mechanical Utilities | Replacement [G30 Site Civil/Mechanical Utilities] | | \$159,386 | |
| G40 Site Electrical Utilities | Replacement [G40 Site Electrical Utilities] | | \$39,84 | |
| G204007 Playing Fields | Replacement [G204007 Playing Fields] | | \$139,463 | |
| G2050 Landscaping | Replacement [G2050 Landscaping] | | \$99,616 | |
| C1030 Fittings and Equipments | Replacement [C1030 Fittings and Equipments] | 2020 | \$35,862 | |
| G204007 Playing Fields | Replacement [G204007 Playing Fields] | 2020 | \$89,654 | |
| D2020 Domestic Water Distribution - DHW Tank | Replacement [D2020 Domestic Water Distribution] | 2020 | \$6,973 | |
| G2020 Parking Lots | Replacement [G2020 Parking Lots] | 2020 | \$75,70 | |
| C3020 Floor Finishes - Painted/Sealed Concrete Floor | Replacement [C3020 Floor Finishes - Painted/Sealed Concrete Floor] | 2020 | \$1,992 | |
| | Backlog + 5 Years | | \$3,369,473 | |
| Date Report Generated | 1/19/2016 | | | |

| Door &Windows | Infrastructure | Interior Finishes | Mechanical | Electrical | Site Work |
|---------------|----------------|-------------------|------------|------------|---|
| \$85,176 | | | | | |
| | | \$65,707 | | | |
| \$91,260 | | | | | |
| | \$395,460 | | | | |
| | | | | \$54,756 | |
| | | \$17,968 | | | |
| | | \$49,211 | | | |
| | | | | | \$67,739 |
| | | | \$155,664 | | |
| | | | \$60,840 | | |
| | | \$79,693 | | | |
| | | | \$15,939 | | |
| | | | | \$3,985 | |
| | | | | \$12,168 | |
| | | | \$133,754 | | |
| | | \$14,942 | | | |
| | | | | \$54,756 | |
| | | | \$22,912 | | |
| | | | \$139,578 | | |
| | | | | \$3,985 | |
| | | | | \$109,578 | |
| | | | \$84,689 | | |
| | \$29,885 | | | | |
| | \$83,678 | | | | |
| | \$139,463 | | | | |
| \$58,406 | | | | | |
| | | | \$19,962 | | |
| | | \$179,309 | | | |
| | | | \$181,712 | | |
| \$21,902 | | | | | |
| | | | | | \$43,831 |
| | | \$79,693 | | | |
| | | \$59,770 | | | |
| | | | | | |
| | | | \$47,816 | | |
| | | | \$25,900 | | |
| | | | | | \$29,885 |
| | | | | | \$159,386 |
| | | | | | \$39,846 |
| | | | | | \$139,463 |
| | | | | | \$99,616 |
| | | \$35,862 | | | , |
| | | , | | | \$89,654 |
| | | | \$6,973 | | \$00,001 |
| | | | φ0,010 | | \$75,708 |
| | | \$1,992 | | | <i></i> ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,, |
| \$256,745 | \$648,486 | \$584,147 | \$895,739 | \$239,228 | \$745,128 |

Note: This report was generated directly from the Ministry of Education Total Capital Planning Solutions (TCPS) database. It provides more information about the Major Facility Needs - 5 Year Projection to supplement Section 2.2 of the School Information Profile.